

Statement of Insulation



House Address	46 Plunket Terrace HAMILTON
Ceiling Insulation	Brand: Knauf /Rockwool Depth: 220mm (Combined)
Meets 2021 Healthy Homes <u>Insulation</u> Requirements	YES
Underfloor Insulation	Brand: Ecotherm R-Value: R1.5
Meets 2021 Healthy Homes <u>Insulation</u> Requirements	YES
Ground Vapour Barrier	YES - Completed
Wall Insulation	Exempt - unable to assess
Smoke Alarms	Number: 2 Location: Lounge/Bedroom Expiry: 2027/2029
Name of Assessor	Jock Caddigan
Date of Insulation/Assessment	3 December 2020

Snug Homes for Rentals – a service by
0800 400 ECO - www.ecoinsulation.co.nz

ecoinsulation
retrofit | renovate | new build | commercial | residential

Notes:-

This statement is based on the observations and records collected by Eco Insulation team members on the day of the assessment/installation. Insulation materials are not fixed and can be disturbed by other trades.

Smoke Alarms can save lives.

The NZ Fire Service state;

Keep smoke alarms clean. Dust and debris can interfere with the alarm's operation so vacuum over and around your smoke alarm regularly. Once a month check the smoke alarm is working by pressing the test button. If you cannot reach the button easily, use a broom handle.

If all is OK you will hear a loud beep or a series of beeps. If you get no response it is most likely the batteries, or the alarm if it is a long-life type, will need to be replaced.

Replace all smoke alarm batteries at least once a year using the required battery. A good way to remember is to replace the batteries at the same time every year, such as the beginning or end of daylight savings