

Statement of Insulation



House Address	6D Edgecumbe Street HAMILTON	
Ceiling Insulation	Brand:	Knauf Earthwool
	R-Value:	R3.6
	Depth:	175mm
Meets RTA <u>Insulation</u> Requirements	YES	
Underfloor Insulation	Brand:	Ecotherm
	R-Value:	R1.5
Meets RTA <u>Insulation</u> Requirements	YES	
Wall Insulation	Exempt as unable to assess	
Smoke Alarms	Number:	2
Name of Assessor	Gary Fowke	
Date of Insulation/Assessment	14 November 2018	

Snug Homes for Rentals – a service by
0800 400 ECO | www.ecoinsulation.co.nz

ecoinsulation
retrofit | renovate | new build | commercial | residential

Notes:-

This statement is based on the observations and records collected by Eco Insulation team members on the day of the assessment/installation. Insulation materials are not fixed and can be disturbed by other trades.

Smoke Alarms can save lives.

The NZ Fire Service state,

Keep smoke alarms clean. Dust and debris can interfere with the alarm's operation so vacuum over and around your smoke alarm regularly. Once a month check the smoke alarm is working by pressing the test button. If you cannot reach the button easily, use a broom handle.

If all is OK you will hear a loud beep or a series of beeps. If you get no response it is most likely the batteries, or the alarm if it is a long life type, will need to be replaced.

Replace all smoke alarm batteries at least once a year using the required battery. A good way to remember is to replace the batteries at the same time every year, such as the beginning or end of daylight savings.